



Map data ©2016 Google 2 mi

Pyramid Network Services, Tannersville Station, Visual Test, 9/20/16. Photo Log

Location 1:

Hunter Mtn Brewery, Rt 23A, (42 11 59.9, -74 11 23.0) Not visible

Location 2:

St Mary's Church, Rt 23.A, (42 12 14.6, -74 12 01.3) Not Visible

Location 3:

Hunter Mtn Trail Head, Stony Clove Rd (42 10 54.5, -74 11 49.3) Not Visible

Location 4: Devil's Path Trail Head (42 09 34.3, -74 12 12.3) Not Visible

Location 5: Rt 23A/Bloomer Rd (42 11 29.5, -74 10 04.4) Not Visible

Location 6: Roaring Kill (42 09 03.5, -74 07 51.3) Not Visible

Location 7: Elka Park Club House (Corner of Pool) (42 09 33.6, -74 09 22.1) Not visible due to trees

Location 8: Entrance at Gillispie Road (42 10 49.1, -74 07 35.0) Not visible

Location 9: All Soul's Church (42 13 27.6, -74 08 02.1) Not visible